

LEGAL NOTICE NO. 233

REPUBLIC OF TRINIDAD AND TOBAGO

THE MUNICIPAL CORPORATIONS ACT, 1990

ORDER

MADE BY THE PRESIDENT UNDER SECTION 7A(5) OF THE MUNICIPAL  
CORPORATIONS ACT, 1990

THE MAYARO/RIO CLARO REGIONAL CORPORATION  
VESTING ORDER, 2000

WHEREAS by virtue of section 7A(1) of the Municipal Corporations Act, <sup>Preamble</sup> 1990 (hereinafter referred to as “the Act”) the land, other property and <sup>Act No. 21 of</sup> any of the rights, privileges, advantages, liabilities and obligations of a <sup>1990</sup> former County Council were transferred to and vested in the State on the 1st day of October, 1991:

And whereas it is provided by section 7A(5) of the Act that the President may by Order transfer to and vest the land, other property and any of the rights, privileges, advantages, liabilities and obligations of a former County Council in any of the several Municipal Corporations:

And whereas it is expedient that the land, other property, rights, privileges, advantages, liabilities and obligations of a former County Council be transferred to and vested in the Mayaro/Rio Claro Regional Corporation.

Now, therefore, the President in pursuance of section 7A(5) of the Act makes the following Order:

Citation            1. This Order may be cited as the Mayaro/Rio Claro  
Regional Corporation Vesting Order, 2000.

Assets to vest    2. The land, other property, rights, privileges,  
in Municipal    advantages, liabilities and obligations set out in the  
Corporation    Schedule are transferred to and vested in the  
Mayaro/Rio Claro Regional Corporation.

(Paragraph 2)

SCHEDULEMAYARO-RIO CLARO REGIONAL CORPORATIONDETAILED SCHEDULE OF ASSETS AND LIABILITIES  
OF MUNICIPAL AND REGIONAL CORPORATION

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>SERVICABLE VEHICLES</b>		
	Nissan Dump Truck - TAN 3988	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Dump Truck - TAE 6706	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Hino Dump Truck - TAK 1066	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Hino Dump Truck - TAJ 5602	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Hino Water Tanker - TAK 1067	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Hino Flat Tray Truck - TAR 1253	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Bedford Winch Truck - TAF 9532	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Bedford Garbage Truck - TAH 3674	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Bedford Garbage Truck - TAH 3675	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Bedford Sewer Disposal Emptier - TAE 2618	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Sewer Disposal Emptier - TAZ 4132	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Leyland Boxer Sewer Disposal Emptier - TY 6634	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Toyota Flat Tray Van - TAE 2673	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Toyota Land Cruiser - PAJ 9023	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Patrol Van - PAF 6733	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Patrol Van - PAK 4704	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ford Flat Tray Van - TZ 9405	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ford Wheel Tractor - TAE 7511	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ford Wheel Tractor - TAF 3278	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ford Wheel Tractor - TAM 7177	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	M.F. Wheel Tractor - TAD 3337	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	M.F. Wheel Tractor - TAD 5540	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer

Assets Category	Assets Description	Assets Location	Responsibilities Centre/Officer Division
<b>FIXED ASSETS</b>	Ford Backhoe - TAE 7857	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	M. F. Backhoe - TAE 5926	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	M. F. Backhoe - TAE 5927	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ingersol Rand Roller - TAA 6002	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Josch Moeller Roller - TAA 2592	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Josch Moeller Roller - TAK 1754	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Josch Moeller Roller - TAK 1758	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Caterpillar Grader - TAG 923	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Caterpillar Track Tractor - D/6	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ford Flat Tray Truck - TAC 6342	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Weeks Popular Trailer - TAG 774	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Weeks Popular Trailer - TAH 8424	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Weeks Popular Trailer - TAH 8425	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Flat Tray Truck - TAJ 7364	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
Weeks Popular Tractor - TBB 2749	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer	
<b>UNSERVICEABLE VEHICLES</b>	Josch Moeller Roller - TAA 2634	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Josch Moeller Roller - TAK 1759	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ingersol Rand Roller - TAA 6003	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Ingersol Rand Roller - TAB 3772	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Mercedes Unimog - TAD 8016	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Toyota Mini Bus - PAD 670	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Toyota Flat Tray Van - TAE 6431	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Nissan Dump Truck - TAE 6705	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Hino Dump Truck - TAK 1065	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Bomag Roller - TAF 3868	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	John Deere Roller - D / 4	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>BUILDINGS</b>		
	<i>Technical Office ( Enclosed Building 25 m x 7 m )</i>	<i>Rio Claro South</i>	<i>Chief Executive Officer</i>
	<i>Works Supervisor III and Transport Office ( Enclosed Building 16 m x 5 m )</i>	<i>Rio Claro South</i>	<i>Chief Executive Officer</i>
	<i>Stores ( Enclosed Building 28 m x 8 m )</i>	<i>Rio Claro South</i>	<i>Chief Executive Officer</i>
	<i>Workshop ( Enclosed Building 13m x 5m ) (Open Area 16 m x 20 m)</i>	<i>Rio Claro South</i>	<i>Chief Executive Officer</i>
	<b>RECREATION GROUNDS</b>		
	<i>Dades/Killdeer - 1.61 hectares</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Liberville - .809 hectares</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro - 1.6 hectares</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Shell - 1.07 hectares</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Jairam Trace - 2.02 hectares</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Navet/Cushe - 2.42 hectares</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Cushe - 1.76 hectares</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Charuma - 2.02 hectares</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Biche/Ortoire - 1.61 hectares</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Plum Mitan - .809 hectares</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Boos - .809 hectares</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Ecclesville - .987 hectares</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Union - 1.85 hectares</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Mafeking - 1.77 hectares</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Ortoire - 2.02 hectares</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mayaro - 1.06 hectares</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>La Savanne - 1.61 hectares</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Guayaguayare - .538 hectares</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Inner Mafeking - .404 hectares</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Old Guayaguayare Road - 1.04 hectares</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>PLAY PARK</b>		
	<i>Edric Connor - 4.04 hectares</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro Children's</i>	<i>Rio Claro South</i>	<i>Chief Executive Officer</i>
	<b>MARKETS &amp; ABBATOIRS</b>		
	<i>Mayaro - 25m x 10m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Meat Stalls - 16 - 1m x 2m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Vegetable Stalls - 36 - 1m x 2m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro - 30m x 8m , 10m x 8m, 12m x 10m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Annex - 55m x 20m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Meat Stalls - 48 - .76m x 1m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Vegetable Stalls - 48 - .76m x 1m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b>PUBLIC CONVENIENCE</b>		
	<i>Rio Claro - Enclosed building 6m x 2.44m</i>	<i>Rio Claro/South</i>	<i>Chief Executive Officer</i>
	<i>Mayaro - Enclosed building 7m x 6m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<b>FAECAL DUMP</b>		
	<i>Faecal Dump - 1.5 Hectares</i>		
	<i>Six (6) Anaerobic Ponds</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b>CEMETERIES</b>		
	<i>Dades/Killdeer - 1.61 hectares</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Fonrose - 1.21 hectares</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro - 3.23 hectares</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Navet/Cushe - 2.02 hectares</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Biche/Ortoire - 1.21 hectares</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Plum Mitan - 809 hectares</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Ecclesville - 1.21 hectares</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Union - 809 hectares</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>CEMETERIES</b>		
	<i>Bristol</i>	- 2.02 hectares	<i>Ortoire/Mafeking</i>
	<i>St. Joseph</i>	- .809 hectares	<i>Ortoire/Mafeking</i>
	<i>Radix</i>	- 1.21 hectares	<i>Mayaro South</i>
	<i>La Savanne</i>	- .404 hectares	<i>Trinity/Guayaguayare</i>
	<b>CREMATORIUM</b>		
	<i>Mafeking Cremation Ground</i>	- 1.91 hectares	<i>Ortoire/Mafeking</i>
	<b>DRAINS</b>		
	<b><i>Ferrier Circular</i></b>		
	<i>Earthen</i>	- 600m	<i>Trinity/Guayaguayare</i>
	<i>Inverted</i>	- 1200m x .45m	-do-
	<i>Box Drain</i>	- 900m x .91m	-do-
	<b><i>Guayaguayare Old Road</i></b>		
	<i>Inverted</i>	- 400m x .45m	<i>Trinity/Guayaguayare</i>
	<b><i>La Savanne Recreation Ground</i></b>		
	<i>Earthen</i>	- 600m	<i>Trinity/Guayaguayare</i>
	<b><i>Rust Road</i></b>		
	<i>Earthen</i>	- 20m	<i>Trinity/Guayaguayare</i>
	<i>Inverted</i>	- 30m x .45m	-do-
	<b><i>Rustville Housing Scheme</i></b>		
	<i>Inverted</i>	- 90m x .45m	<i>Trinity/Guayaguayare</i>
	<i>Box Drain</i>	- 30m x .91m	-do-
	<b><i>La Savanne Circular Trace</i></b>		
	<i>Inverted</i>	- 300m x .45m	<i>Trinity/Guayaguayare</i>
	<i>Box Drain</i>	- 600m x .91m	-do-
	<b><i>Nurse Trace</i></b>		
	<i>Earthen</i>	- 600m	<i>Trinity/Guayaguayare</i>
	<i>Inverted</i>	- 30m x .45m	-do-
	<i>Box Drain</i>	- 100m x .76m	-do-

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<i>Yespy Road</i>		
	Earthen - 900m	Trinity/Guayaguayare	Chief Executive Officer
	<i>Yespy Extension Trace</i>		
	Earthen - 2400m	Trinity/Guayaguayare	Chief Executive Officer
	<i>Lyng &amp; Tyndale Streets</i>		
	Earthen - 200m	Trinity/Guayaguayare	Chief Executive Officer
	<i>Alexis Street</i>		
	Inverted - 30m x .45m	Mayaro North	Chief Executive Officer
	Box Drain - 45m x .91m	-do-	-do-
	<i>Edward Street</i>		
	Earthen - 50m	Mayaro North	Chief Executive Officer
	Inverted - 25m x .45m	-do-	-do-
	<i>Solomon Street</i>		
	Earthen - 400m	Mayaro North	Chief Executive Officer
	Inverted - 60m x .45m	-do-	-do-
	Box Drain - 30m x .76m	-do-	-do-
	<i>St. Joseph Road</i>		
	Earthen - 1200m	Mayaro North	Chief Executive Officer
	<i>Lewis &amp; Sucre Street</i>		
	Earthen - 800m	Mayaro North	Chief Executive Officer
	Inverted - 300m	-do-	-do-
	Box Drain - 300m x .76m	-do-	-do-
	<i>Peter Hill Trace</i>		
	Box Drain - 120m x .76m	-do-	-do-
	<i>Alice Trace</i>		
	Earthen - 400m	Mayaro Central	Chief Executive Officer
	<i>Begorat Trace</i>		
	Earthen - 800m	Mayaro Central	Chief Executive Officer
	Inverted - 600m x .45m	-do-	-do-
	<i>Cedar Grove Road</i>		

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Faecal Dump Road</i></b>		
	<i>Earthen - 600m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>Gregorio Trace</i></b>		
	<i>Earthen - 700m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>Liet Street</i></b>		
	<i>Inverted - 200m x .45m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 60m x .76m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Naparima Mayaro Old Road</i></b>		
	<i>Earthen - 600m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>New Trace</i></b>		
	<i>Earthen - 450m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>Peter Hill Extension Trace</i></b>		
	<i>Inverted - 300m x .45m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>St. Anns Trace</i></b>		
	<i>Earthen - 600m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Sylvan Trace</i></b>		
	<i>Earthen - 180m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<b><i>Tyndale Street</i></b>		
	<i>Inverted - 60m x .45m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 60m x .76m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Bon Espoire Road</i></b>		
	<i>Earthen - 800m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Church Road</i></b>		
	<i>Inverted - 550m x .45m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 600m x .91m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Eccles Road</i></b>		
	<i>Earthen - 800m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 120m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<i>Box Drain - 150m x .76m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Edghill Road</i></b>		
	<i>Earthen - 1000m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Gould Street</i></b>		
	<i>Earthen 300m, 60m x .45m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Higgins Trance</i></b>		
	<i>Earthen 30m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Plaisance Housing Scheme</i></b>		
	<i>Inverted - 2600m x .45m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Maloney Road</i></b>		
	<i>Earthen - 3200m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 70m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<i>Box Drain - 60m x .91m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Radix Cemetery Trace</i></b>		
	<i>Earthen - 400m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Tang Trace</i></b>		
	<i>Earthen - 1400m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Taylor Street</i></b>		
	<i>Inverted - 200m x .45m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<b><i>Ablack Trace</i></b>		
	<i>Earthen - 1500m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Abass Trace</i></b>		
	<i>Earthen - 400m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Bhajnandass Trace</i></b>		
	<i>Earthen - 800m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Rhagrattee Trace</i></b>		
	<i>Earthen - 700m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 1000m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Balata Trace</i></b>		
	<i>Earthen - 500m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Coleuso Trace</i></b>		
	<i>Earthen - 600m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Cemetery Trace</i></b>		
	<i>Earthen - 100m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Charuma Trace</i></b>		
	<i>Earthen - 500m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Charuma Junction Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 3000m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Cushe Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 400m x .76m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Dos Ramos Trace</i></b>		
	<i>Earthen - 250m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Euroze Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Jankee Trace</i></b>		
	<i>Earthen - 1200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Jankee Branch Trace</i></b>		
	<i>Earthen - 120m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Jairam Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 400m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Jairam Branch Trace</i></b>		
	<i>Earthen - 75m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Knollhill Trace</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Lutchminia Trace</i></b>		
	<i>Earthen - 600m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Lawerence Jones Trace</i></b>		
	<i>Earthen - 3000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Mahabalsingh Trace</i></b>		
	<i>Earthen - 4000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 600m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Mahabalsingh Branch Trace #1</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Mahabalsingh Branch Trace #2</i></b>		
	<i>Earthen -</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 800m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Mahabalsingh Extension Trace</i></b>		
	<i>Earthen - 900m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Oliver Trace</i></b>		
	<i>Earthen - 400m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Oliver Branch Trace</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Ragoonanan Trace</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Rampaul Trace</i></b>		
	<i>Earthen - 900m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 30m x .45m</i>	<i>-do-</i>	<i>-do-</i>
	<b><i>Rambhoratt Trace</i></b>		
	<i>Earthen - 30m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Reid Trace</i></b>		
	<i>Earthen - 330m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Sarran Trace</i></b>		
	<i>Earthen - 100m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Ross Trace</i></b>		
	<i>Earthen - 150m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Earthen - 1200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sunair Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sunair Branch Trace</i></b>		
	<i>Earthen - 100m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sackee Trace</i></b>		
	<i>Earthen - 1200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sampath Trace</i></b>		
	<i>Earthen - 120m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sancho Trace</i></b>		
	<i>Earthen - 3.2m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Shee Young Trace</i></b>		
	<i>Earthen - 500m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Sirju Extension Trace</i></b>		
	<i>Earthen - 400m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Tabaquite/Charuma Trace</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Trace Off Charuma Junction Trace</i></b>		
	<i>Earthen - 20m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Margaret Harry Trace</i></b>		
	<i>Earthen - 120m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Hamilton Trace</i></b>		
	<i>Earthen - 1200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Hamilton Branch Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Killdeer Branch Trace</i></b>		
	<i>Earthen - 400m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Charuma Road</i></b>		
	<i>Earthen - 1000m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Cushe Village Street</i></b>		
	<i>Earthen - 200m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<b><i>Biche Village Street</i></b>		
	<i>Inverted - 1657m x .45m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Riche Settlement Street</i></b>		
	<i>Earthen - 600m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 2000m x .45m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Crisendial Trace</i></b>		
	<i>Earthen - 457m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 940m x .45m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Heminez Trace</i></b>		
	<i>Earthen - 1026m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Joseph Trace</i></b>		
	<i>Earthen - 274m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Kawlesser Trace</i></b>		
	<i>Box Drain - 600m x .76m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 175m x .45m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Lassalle Trace</i></b>		
	<i>Earthen - 900m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Lewis Trace</i></b>		
	<i>Earthen - 420m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>O'Brian Trace</i></b>		
	<i>Earthen - 1055m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Peter Trace</i></b>		
	<i>Earthen - 200m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Prudence Trace</i></b>		
	<i>Earthen</i> - 480m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Rahim Trace</i></b>		
	<i>Earthen</i> - 300m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Raulal Trace</i></b>		
	<i>Earthen</i> - 200m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Settlement Trace #2</i></b>		
	<i>Earthen</i> - 859m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 180m x .45	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Jauke Trace</i></b>		
	<i>Earthen</i> - 420m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Jauke Branch Trace</i></b>		
	<i>Earthen</i> - 130m	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<b><i>Lalla Street</i></b>		
	<i>Inverted</i> - 65m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Roble Grove Road</i></b>		
	<i>Earthen</i> - 600m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 200m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Rio Claro/Mayaro Road</i></b>		
	<i>Earthen</i> - 500m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 3000m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Pond Road</i></b>		
	<i>Earthen</i> - 500m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Central Brauch Road</i></b>		
	<i>Earthen</i> - 500m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 3000m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Hibiscus Arch Road</i></b>		
	<i>Earthen</i> - 1200m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 250m	<i>Ecclesville</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<i>Archer Trace</i>		
	Earthen - 200m	Ecclesville	Chief Executive Officer
	<i>Agostini Settlement Tr.#1</i>		
	Earthen - 200m	Ecclesville	Chief Executive Officer
	<i>Agostini Settlement Tr.#2</i>		
	Earthen - 150m	Ecclesville	Chief Executive Officer
	<i>Agostini Road</i>		
	Earthen - 1000m	Ecclesville	Chief Executive Officer
	<i>Belasny Trace</i>		
	Earthen - 2000m	Ecclesville	Chief Executive Officer
	<i>Cadiz Trace</i>		
	Earthen - 830m	Ecclesville	Chief Executive Officer
	<i>Cazaban Trace</i>		
	Earthen - 400m	Ecclesville	Chief Executive Officer
	<i>Deep Ravine Trace</i>		
	Earthen - 60m	Ecclesville	Chief Executive Officer
	<i>Mowlah Trace</i>		
	Earthen - 100m	Ecclesville	Chief Executive Officer
	<i>Mile End Road</i>		
	Earthen - 1700m	Ecclesville	Chief Executive Officer
	Inverted - 200m	Ecclesville	Chief Executive Officer
	<i>Muctarsingh Trace</i>		
	Earthen - 400m	Ecclesville	Chief Executive Officer
	<i>Noel Trace</i>		
	Earthen - 300m	Ecclesville	Chief Executive Officer
	<i>Rajpaul Trace</i>		
	Earthen - 1200m	Ecclesville	Chief Executive Officer
	<i>Rio Claro Trace</i>		
	Earthen - 1800m	Ecclesville	Chief Executive Officer

**Mayaro/Rio Claro Regional Corporation Vesting Order, 2000**

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Rampersad Trace</i></b>		
	<i>Earthen - 800m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Rio Claro-Mayara Road</i></b>		
	<i>Earthen - 5000m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 1200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Sarvansingh Trace</i></b>		
	<i>Earthen - 600m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Teemul Trace</i></b>		
	<i>Earthen - 800m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Trebenny Trace</i></b>		
	<i>Earthen - 500m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Qudhan Road</i></b>		
	<i>Inverted - 150m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Ecclesville Settlement Street</i></b>		
	<i>Earthen - 150m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 100m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Mac Mohan Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Legendre Trace</i></b>		
	<i>Earthen - 3500m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Boos Settlement Trace</i></b>		
	<i>Earthen - 1000m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Mahogany Road</i></b>		
	<i>Earthen - 75m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Mac Mohan Extension Trace</i></b>		
	<i>Earthen - 120m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 30m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Pattigin Branch Trace</i></b>		
	<i>Earthen - 120m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Bamboo Road</i></b>		
	<i>Earthen - 400m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Ecclesville Village Street</i></b>		
	<i>Earthen - 200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 1200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Legendre Road</i></b>		
	<i>Earthen - 100m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 1200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Clear Water Road</i></b>		
	<i>Earthen - 700m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 800m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Rio Claro-Mayaro Branch Road</i></b>		
	<i>Earthen - 1200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Co-operation Road</i></b>		
	<i>Inverted - 400m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Lagoon Road</i></b>		
	<i>Earthen - 125m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 100m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Unity Road</i></b>		
	<i>Earthen - 50m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>Guaya Patch Road</i></b>		
	<i>Earthen - 250m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<b><i>El Guayanapo Trance</i></b>		
	<i>Earthen - 100m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Mora Settlement Trance</i></b>		
	<i>Earthen - 287m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 100m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Paole Syndicate Village Streets</i></b>		
	<i>Inverted - 400m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 100m x .61m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>

## Mayaro/Rio Claro Regional Corporation Vesting Order, 2000

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division:</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Rio Claro Village Street</i></b>		
	<i>Inverted - 1500m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 900m x .91m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>El Guayauapo (NHA Road)</i></b>		
	<i>Inverted - 2520m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Poole Valley Trace</i></b>		
	<i>Earthen - 4000m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 400m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Abdul Trace</i></b>		
	<i>Earthen - 4000m x .2m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Old Mayaro Road</i></b>		
	<i>Earthen - 1200m x .2m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Absalom Trace</i></b>		
	<i>Earthen - 120m x .2m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Abdul Branch Trace</i></b>		
	<i>Earthen - 100m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Church Village Streets</i></b>		
	<i>Earthen - 300m x .2m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m x .45</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Libertyville Village Streets</i></b>		
	<i>Earthen - 400m x .5m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 300m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Old Mayaro Branch Trace</i></b>		
	<i>Earthen - 100m x .4m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m x .45m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Old Railway Road</i></b>		
	<i>Earthen - 100m x .6m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Trace Off Old Mayaro Road</i></b>		
	<i>Earthen - 100m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<b><i>Lazzari Road</i></b>		
	<i>Earthen - 1500m x .4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 500m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Lynn Trace</i></b>		
	<i>Earthen - 400m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Matthew Trace</i></b>		
	<i>Earthen - 500m x .4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Moonkey Trace</i></b>		
	<i>Earthen - 800m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Mahaugnsingh Branch Trace</i></b>		
	<i>Earthen - 1200m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 100m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Mathura Street</i></b>		
	<i>Inverted - 200m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Nathni Street</i></b>		
	<i>Inverted - 100m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Prada Settlement Trace</i></b>		
	<i>Earthen - 800m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m x .45</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Paymar Trace</i></b>		
	<i>Earthen - 600m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 300m x .46m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 100m x .61m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Paymar Branch Trace</i></b>		
	<i>Earthen - 2000m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Paole Valley Trace</i></b>		
	<i>Earthen - 4000m x .6m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 900m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Pariag Trace</i></b>		
	<i>Earthen</i> - 2000m x .5m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Ragoo Trace</i></b>		
	<i>Earthen</i> - 800m x .4m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Rajali Street</i></b>		
	<i>Earthen</i> - 200m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Box Drain</i> - 60m x .91m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Ramanan Street</i></b>		
	<i>Inverted</i> - 150m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Riverside Road</i></b>		
	<i>Earthen</i> - 4000m x .6m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 900m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>San Pedro Railway Diversion Trace</i></b>		
	<i>Earthen</i> - 1500m x .5m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Suphariya Trace</i></b>		
	<i>Earthen</i> - 900m x .4m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Suphariya Branch Trace</i></b>		
	<i>Earthen</i> - 200m x .5m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>San Pedro Railway Trace</i></b>		
	<i>Earthen</i> - 1800m x .5m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 200m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Risson Street</i></b>		
	<i>Inverted</i> - 50m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Reckles Trace</i></b>		
	<i>Earthen</i> - 700m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Regesse Trace</i></b>		
	<i>Earthen</i> - 700m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Rhoopsingh Trace</i></b>		
	<i>Earthen - 500m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Rhoopsingh Branch Trace</i></b>		
	<i>Earthen - 200m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Beharry Trace</i></b>		
	<i>Earthen - 2000m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 250m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Campbell Trace</i></b>		
	<i>Earthen - 5000m x .5m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 300m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Carrere Diversion Trace</i></b>		
	<i>Earthen - 100m x .4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Carrere Road</i></b>		
	<i>Earthen - 1200m x .4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 2000m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Dades Trace</i></b>		
	<i>Earthen - 1200m x .4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Dades Extension Trace # 1, 2 &amp; 3</i></b>		
	<i>Earthen - 2500m x .46m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 400m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Dades Settlement Trace</i></b>		
	<i>Earthen - 800m x .46m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 300m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Elahie Street</i></b>		
	<i>Earthen - 200m x .46m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>El Rosario Trace</i></b>		
	<i>Earthen - 100m x .46m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 50m x .45m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b><i>Glad Street</i></b>		
	<i>Earthen</i> - 100m x .5m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 200m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Gosine Street</i></b>		
	<i>Earthen</i> - 100m x .46m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 150m x .6m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Idu Street</i></b>		
	<i>Earthen</i> - 200m x .6m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 120m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>John Andrew Street</i></b>		
	<i>Earthen</i> - 60m x .6m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 100m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Killdeer Trace</i></b>		
	<i>Earthen</i> - 800m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Inverted</i> - 350m x .45m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Liddle Low Street</i></b>		
	<i>Inverted</i> - 100m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Latchram Trace</i></b>		
	<i>Earthen</i> - 800m x .6m	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<b><i>Bristol Road</i></b>		
	<i>Earthen</i> - 1500m x .5m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b><i>Basil Trace</i></b>		
	<i>Earthen</i> - 1100m x .4m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b><i>Bhagoo Trace</i></b>		
	<i>Earthen</i> - 600m x .5m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b><i>Bhagoo Branch Trace</i></b>		
	<i>Earthen</i> - 300m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b><i>Cadette Trace</i></b>		
	<i>Earthen</i> - 180m x .4m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<b><i>Cascadoux Trace</i></b>		
	<i>Earthen</i> - 1654m	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<i>Chrysostem Trace</i>		
	<i>Earthen - 400m x .4m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Dhunda Trace</i>		
	<i>Earthen - 20m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Fields Trace</i>		
	<i>Earthen - 400m x .4m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Guppy Hill</i>		
	<i>Earthen - 700m x .46m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Logwood Trace</i>		
	<i>Earthen - 600m x .5m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 200m x .45m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mafeking Road</i>		
	<i>Earthen - 4000m x .5m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 1200m x .46m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 700m x .91m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mafeking Branch Road</i>		
	<i>Earthen - 1800m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mafeking Road (Manz. End)</i>		
	<i>Earthen - 500m x .4m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>North West Trace</i>		
	<i>Earthen - 1500m x .4m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Ortoire Hill Road</i>		
	<i>Earthen - 1800m x .5m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 60m x .43m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Ortoire Recreation Ground Road</i>		
	<i>Earthen - 200m x .4m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Inverted - 100m x .45m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Box Drain - 60m x .91m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>

## Mayaro/Rio Claro Regional Corporation Vesting Order, 2000

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>DRAINS</b>		
	<b>Point Radix Road</b>		
	Earthen - 1500m x .4m	Ortoire/Mafeking	Chief Executive Officer
	Inverted - 40m x .45m	Ortoire/Mafeking	Chief Executive Officer
	Box Drain - 75m x .91m	Ortoire/Mafeking	Chief Executive Officer
	<b>Ross Trace</b>		
	Earthen - 400m x .5m	Ortoire/Mafeking	Chief Executive Officer
	<b>Siendath Trace</b>		
	Earthen - 1600m x .4m	Ortoire/Mafeking	Chief Executive Officer
	<b>Union Road</b>		
	Earthen - 1100m x .5m	Ortoire/Mafeking	Chief Executive Officer
	Inverted - 60m x .45m	Ortoire/Mafeking	Chief Executive Officer
<b>FIXED ASSETS</b>	<b>ROADS</b>		
	Charuma Road, 1690m pitch	Navel/Charuma	Chief Executive Officer
	Cocoa Fermentary Road, 393 Pitch, 503 Natural Soil	Navel/Charuma	Chief Executive Officer
	Bristol Road, 779m Oilsand	Ortoire/Mafeking	Chief Executive Officer
	Mafeking Road, 4336m Asphalt	Ortoire/Mafeking	Chief Executive Officer
	Mafeking Branch Road, 1305m Oilsand, 120m Gravel	Ortoire/Mafeking	Chief Executive Officer
	Mafeking Road (Manz. End), 1028m Pitch	Ortoire/Mafeking	Chief Executive Officer
	Ortoire Hill Road, 1000m Asphalt, 492m Oilsand	Ortoire/Mafeking	Chief Executive Officer
	Ortoire Rec. Ground Road, 215m Asphalt	Ortoire/Mafeking	Chief Executive Officer
	Point Radix Road, 400m Asphalt, 1332m Oilsand	Ortoire/Mafeking	Chief Executive Officer
	Rio Claro-Mayaro Road (Mafeking Road) 380m Oilsand, 1812m Natural Soil	Ortoire/Mafeking	Chief Executive Officer
	Rio Claro-Mayaro Road (Bristol End) 725m Oilsand, 1485m Pitch	Ortoire/Mafeking	Chief Executive Officer
	Rio Claro-Mayaro Road (Union End) 300m Gravel, 1968 Natural Soil	Ortoire/Mafeking	Chief Executive Officer
	Union Road, 450 Asphalt, 472m Oilsand	Ortoire/Mafeking	Chief Executive Officer
	St. Joseph Road, Asphalt 323m, Unpaved 36m.	Mayaro-North	Chief Executive Officer

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>ROADS</b>		
	<i>Cedar Grove Road, Asphalt 1600m, Pitch 3324m, Natural Soil 122m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Faecal Dump Road, Pitch 364m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Naparima-Mayaro Old Road, Pitch 45m, Natural Soil 303m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Carrere Road, 1680 Asphalt</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lazzari Road, 2233m Pitch</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Riverside Road, 882 Asphalt, 2386 Pitch</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Old Mayaro Road, 1188m Pitch</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Old Railway Road, 92m Asphalt, 457 Oilsand, 1311m Gravel</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>El Guayanapo, 1260m Asphalt (NHA Roads)</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Bon Espoire Road, Pitch 672m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Church Road, Asphalt 708m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Edghill Road, Oilsand 120m, Pitch 429m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Road, Asphalt 600m, Pitch 1381m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>St. Anns Road, Asphalt 720m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Maloney Road, Asphalt 400m, Unpaved 2648m, 153m, Natural Soil 92m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Ferrier Cir. Road, Asphalt 1652m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Guayaguayare Old Road, Asphalt 473m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>La Savanne Rec. Grd. Road, Pitch 92m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Rust Road, Pitch 112m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Schooners Road, Pitch 1283m, Natural Soil 305m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Trinity Road, Pitch 1084</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Vespry Road, Pitch 1177m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Mahogany Road, Pitch 97m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Oudhan Road, Asphalt 70m, Pitch 494m, Natural Soil 564m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Bamboo Road, Pitch 399m, Natural Soil 399m, 503m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Legendre Road, Pitch 2415m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>

## Mayaro/Rio Claro Regional Corporation Vesting Order, 2000

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>ROADS</b>		
	<i>Clear Water Road, Asphalt 1400m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro-Mayaro Branch Road, Pitch 732m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Co-operation Road, Pitch 228m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Lagoon Road, Pitch 372m, Natural Soil 457m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Unity Road, Pitch 137m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Guava Patch Road, Pitch 655m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Roble Grove Road, Asphalt 1080m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro-Mayaro Road, Asphalt 5634m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Pond Road, Pitch 1101m, Natural Soil 444m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Central Branch Road, Pitch 793m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Hibiscus Arch Road, Pitch 1270m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Agostini Road, Asphalt 918m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Mile End Road, Oilsand 1482m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro-Mayaro Road, Asphalt 1569m, Pitch 4049m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trace Off Rio Claro Mayaro Road, Natural Soil 244m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Fitts Road, Pitch 1771m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Lassalle Road, Pitch 2527</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Martin Saza Road, Pitch 1610m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Caltoo Road, Pitch 1005m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Caltoo Road Ext, Natural Soil 404</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Wade Road, Pitch 2625m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Wade Road Ext. Pitch 630m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
<b>FIXED ASSETS</b>	<b>STREETS</b>		
	<i>Liet Street, Asphalt 120m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Pierreville Street, Asphalt 652m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Tyndale Street, Asphalt 180m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>STREETS</b>		
	<i>Alexis Street, Unpaved 36m, Asphalt 323m</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>Edward Street, Oilsand 83m, Natural Soil 90m</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>Solomon Street, Pitch 556m</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>Lewis &amp; Sucre Streets, Asphalt 706m</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>Lyng &amp; Tyndale Streets, Pitch 130m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Gould Street, Asphalt 932m, Unpaved 70m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Gill Street, Pitch 542m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Taylor Street, Pitch 158m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Charuma Village Street, Asphalt 195m, Natural Soil 18m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Cushe Village Street, Asphalt 372, Gravel 168m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Biche Village Street, Asphalt 1600m, 534m Oilsand</i>	<i>Biche/Plum Mitán</i>	<i>Chief Executive Officer</i>
	<i>Biche Settlement Street, Asphalt 324m, Oilsand 971m, Natural Soil 1337m</i>	<i>Biche/Plum Mitán</i>	<i>Chief Executive Officer</i>
	<i>Lassalle Village Street, Natural Soil 274m</i>	<i>Biche/Plum Mitán</i>	<i>Chief Executive Officer</i>
	<i>Ecclesville Settlement Street, Pitch 271m, Natural Soil 43m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Ecclesville Village Street, Asphalt 724m, Pitch 723m, Unpaved 61m, Natural Soil 692m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Lalla Street, Asphalt 76m, Natural Soil 152m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Panchoo Street, Pitch 113m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Poole Syndicate Village Street, Asphalt 945m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro Village Street, Asphalt 1844m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Church Village Streets, Asphalt 700m, Pitch 50m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Liberville Village Streets, Asphalt 90m, Pitch 697m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Bissoon Street, Pitch 51m, Natural Soil 120m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>STREETS</b>		
	<i>Elahie Street, Natural Soil 225m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Glod Street, Asphalt 105m, Natural Soil 315m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Gosine Street, Asphalt 177m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Idu Street, Asphalt 90m, Natural Soil 343m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>John Andrew Street, Asphalt 126m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Liddlelow Street, Asphalt 137m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mathura Street, Asphalt 135m, Natural Soil 60m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Nathai Street, Asphalt 165m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Rajali Street, Asphalt 165m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Ramnanan Street, Asphalt 258m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Rancharan Street, Natural Soil 61m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>La Savanne Circular Trace, 1146m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Nurse Trace, Asphalt 100m, 409m pitch</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Vespry Trace, Pitch, 1123, Natural Soil 622m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Vespry Extension Trace, Asphalt 200m, Natural Soil, 902m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace, 1048 Natural Soil</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Huggins Trace, Pitch 648m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Hygüe Trace, Natural Soil 304m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Radix Cemetery Trace, 534 Pitch</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Tang Trace, Pitch 808m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Alice Trace, Pitch 227m, Natural Soil 409m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Begorat Trace, Asphalt 575m, Pitch 400m, Natural Soil 609, Unpaved 106m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Gregerio Trace, Pitch 495m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>New Trace, Pitch 214m, Natural Soil 61m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Peter Hill Extension Trace, Asphalt 475m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>St. Anns Trace, Pitch 92m, Natural Soil 145m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Sylvan Trace, Pitch 92m, Natural Soil 183m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Thomas Trace, Pitch 153m, Natural Soil 130m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Chotai Trace, Natural Soil 274m</i>	<i>Mayaro South</i>	<i>Chief Executive Officer</i>
	<i>Peter Hill Trace, Asphalt 461m</i>	<i>Mayaro North</i>	<i>Chief Executive Officer</i>
	<i>Albert Trace, Natural Soil 762m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Beckles Trace, Pitch 534m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Begesse Trace, Pitch 610m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Bhoopsingh Trace, Oilsand 427m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Bhoopsingh Branch Trace, Pitch 195m, Natural Soil 430m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Beharry Trace, Asphalt 30m, Pitch 2742m, Natural Soil 600m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Carenage Trace, Natural Soil 160m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Campbell Trace, Oilsand 3200m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Carrere Diversion Trace, Gravel 378m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Dades Trace, Pitch 112m, Gravel 378m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Dades Extension Trace Nos. 1, 2 &amp; 3, Asphalt 122m, Pitch 1941m, Natural Soil 173m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Dades Settlement Trace, Asphalt 628m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>El Rosario Trace, Asphalt 30m, Pitch 60m, Natural Soil 30m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Killdeer Trace, Asphalt 213m, Pitch 2318m, Natural Soil 1341m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Latchram Trace, Pitch 720m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lazzari Extension Trace, Pitch 732m, Natural Soil 60m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lazzari Diversion Trace, Pitch 230m, Natural Soil 88m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lyng Trace, Oilsand 1794m, Natural Soil 2672m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mahadaya Trace, Natural Soil, 610m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mathew Trace, Oilsand 457m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Moonkey Trace, Pitch 630m, Natural Soil 235m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Mahangasingh Trace, Oilsand 1372m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mahangasingh Branch Trace, Oilsand 183m, Natural Soil 719m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Prada Settlement Trace, Asphalt 320m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Paymar Trace, Asphalt 792m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Paymar Branch Trace, Asphalt 120m, Pitch 1860m, Natural Soil 1980m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Pinder Trace, Pitch 320m, Natural soil 609m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace, Oilsand 3445m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Pariag Trace, Asphalt 1188m, Oilsand 360m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Ragoo Trace, Pitch 600m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>San Pedro Branch Trace, Natural Soil 210m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>San Pedro Trace, Oilsand 1470m, Oilsand 603m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>San Pedro Railway Diversion Trace, Pitch 1119m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Suphariya Trace, Pitch 1037m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Suphariya Branch Trace, Pitch 60m, Gravel 318m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>San Pedro Railway Trace, Pitch 1620m Natural Soil 180m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Trace off Naparima Mayaro Road, Gravel 300m, Natural Soil 183m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Trace off Naparima Mayaro Road - 23-3/4mm - 24mm, Gravel 125m, Natural Soil 213m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Woodley Trace, Pitch 366m, Natural Soil 567mm</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Basil Trace, Pitch 667m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Bhagoo Trace, Oilsand 340m, Natural Soil 727m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Bhagoo Branch Trace, Natural Soil 763m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Cadette Trace, Oilsand 90m, Natural Soil 515m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Cascadoux Trace, Oilsand 1654m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Cascadoux Branch Trace, Natural Soil 151m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Chrysostom Trace, Pitch 200m, Natural Soil 250m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Dhunda Trace, Natural Soil 424m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Fields Trace, Oilsand 245m, Gravel 30m, Natural Soil 90m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Guppy Hill Trace, Oilsand 455m, Natural Soil 212m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Horril Trace, Natural Soil 333m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Kabootarie Trace, Natural Soil 120m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Kruger Trace, Oilsand 136m, Natural Soil 1045m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Logwood Trace, Oilsand 628m, Natural Soil 120m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>North West Trace, Oilsand 1078m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Ross Trace, Pitch 242m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Sieudath Trace, Asphalt 450m, Pitch 472m</i>	<i>Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>El Guayanapo Trace, Oilsand 305m, Natural Soil 61m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Mora Settlement Trace, Pitch 387m, Natural Soil 1869m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace, Asphalt 805m, Pitch 1939m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Abdul Trace, Oilsand 2214m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Absalom Trace, Asphalt 75m, Pitch 70m, Natural Soil 152m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Abdul Branch Trace, Natural Soil 137m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Old Mayaro Trace, Natural Soil 1817m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Old Mayaro Branch Trace, Pitch 402m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Trace opposite Old Mayaro Road, Asphalt 90m, Natural Soil 367m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Branch Trace, Natural Soil 457m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>
	<i>Trace off Old Mayaro Road, Gravel 92m, Natural Soil 305m</i>	<i>Rio Claro</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	Unnamed Trace at 25-1/2mm - Naparina Mayaro Road, Pitch 97m	Rio Claro	Chief Executive Officer
	Boos Settlement Trace, Pitch 497m, Natural Soil 58.5m	Ecclesville	Chief Executive Officer
	Legendre Trace, Pitch 1829m	Ecclesville	Chief Executive Officer
	Mac Mohan Trace, Pitch 753m	Ecclesville	Chief Executive Officer
	Mac Mohan Extension Trace, Pitch 61m Unpaved 137m, Natural Soil 329m	Ecclesville	Chief Executive Officer
	North Boundary Trace, Natural Soil 1573m	Ecclesville	Chief Executive Officer
	Pattigun Trace, Natural Soil 1259m	Ecclesville	Chief Executive Officer
	Pattigun Branch Trace, Pitch 40m, Natural Soil 228m	Ecclesville	Chief Executive Officer
	Titus Trace, Natural Soil 960m	Ecclesville	Chief Executive Officer
	Archer Trace, Unpaved 214m, Natural Soil 3133m	Ecclesville	Chief Executive Officer
	Agostini Settlement Trace #1, Asphalt 150m, Pitch 50m, Natural Soil 300m	Ecclesville	Chief Executive Officer
	Agostini Settlement Trace #2, Asphalt 80m, Pitch 200m	Ecclesville	Chief Executive Officer
	Bolasaw Trace, Pitch 2140m	Ecclesville	Chief Executive Officer
	Cadiz Trace, Pitch 532m	Ecclesville	Chief Executive Officer
	Cazabon Trace, Pitch 60m, Natural Soil 1200m	Ecclesville	Chief Executive Officer
	Deep Ravine Trace, Asphalt 292m, Unpaved 48m	Ecclesville	Chief Executive Officer
	Mowlah Trace, Pitch 30m, Natural Soil 568m	Ecclesville	Chief Executive Officer
	Mile End Extension Trace, Natural Soil 549m	Ecclesville	Chief Executive Officer
	Mucktarsingh Trace, Pitch 259m, Natural Soil 195m	Ecclesville	Chief Executive Officer
	Moonan Trace, Pitch 60m, Natural Soil 200m	Ecclesville	Chief Executive Officer
	Noel Trace, Pitch 115m, Natural Soil 755m	Ecclesville	Chief Executive Officer
	Noel Branch Trace, Natural Soil 414m	Ecclesville	Chief Executive Officer
	Rajpaul Trace, Pitch 797m, Natural Soil 1489m	Ecclesville	Chief Executive Officer

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Rio Claro Trace, Asphalt 60m, Pitch 2406m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro Branch Trace, Natural Soil 366m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rampersad Trace, Pitch 614m, Natural Soil 601m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Sarwansingh Trace, Pitch 671m, Natural Soil 720m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Teemul Trace, Pitch 537m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Trace, Pitch 381m, Natural Soil 1030m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Branch Trace, Natural Soil 848m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Bharat Extension Trace, Natural Soil 535m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Chin Wing Trace, Natural Soil 838m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Crisendial Trace, Pitch 457m, Natural Soil 732m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Fitts Trace, Natural Soil 91m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Greenaway Trace, Natural Soil 244m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Heminez Trace, Pitch 549m, Gravel 61m, Natural Soil 416m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Joseph Trace, Natural Soil 279m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Kowlessar Trace, Asphalt 526m, Pitch 175m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Lassalle Trace, Pitch 945m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Marcano Trace, Pitch 1006m, Natural Soil 76m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Martin Saza Trace, Pitch 1146m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Patto Trace, Pitch 615m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Quarry Trace, Natural Soil 427m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Ramdhanie Trace, Natural Soil 831m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Ramjit Trace, Pitch 387m, Gravel 183m, Natural Soil 598m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Ramjit Branch Trace, Pitch 244m, Natural Soil 365m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Soomiah Trace, Pitch 445m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Seebarandass Trace, Natural Soil 282m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>

## Mayaro/Rio Claro Regional Corporation Vesting Order, 2000

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Villafana Trace, Pitch 610m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Trace off Kowlessar Trace, Natural Soil 651m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Brigand Hill Trace, Pitch 800m, Natural Soil 175m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Caltoo Trace, Pitch 1570m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Cushe Trace, Pitch 500m, Natural Soil 460m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Kallie Trace, Natural Soil 195m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Lagoon Trace, Pitch 650m, Natural Soil 72m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Lewis Trace, Pitch 420m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>O'Brien Trace, Pitch 1055m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Peter Trace, Pitch 200m, Natural Soil 730m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Prudence Trace, Pitch 480m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Rahim Trace, Pitch 300m, Natural Soil 600m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Ramlal Trace, Pitch 200m, Natural Soil 350m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Settlement Trace #2, Pitch 859m, Asphalt 180m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Settlement Trace #1, Natural Soil 239m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Jankee Trace, Pitch 420m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Jankee Branch Trace, Pitch 130m, Natural Soil 200m</i>	<i>Biche/Plum Mitan</i>	<i>Chief Executive Officer</i>
	<i>Sumair Branch Trace, Pitch 195m, Gravel 152m, Natural Soil 430m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sackeer Trace, Pitch 622m, Natural Soil 174m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sirjue Trace, Natural Soil 1073m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sampath Trace, Pitch 122m, Gravel 30.5m, Natural Soil 365.5m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sanchoo Trace, Natural Soil 168m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Shee Young Trace, Pitch 229m, Gravel 94.5m, Natural Soil 609.5m</i>	<i>Navel/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Sirjue Extension Trace, Pitch 558m, Gravel 256m, Natural Soil 558m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sirjue Diversion Trace, Natural Soil 1121m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Tuerro Trace, Pitch 207m, Gravel 30.5m, Natural Soil 2018m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Tabaquite Charuma Trace, Gravel 287m, Natural Soil 2793m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Trace off Charuma Junction Trace, Pitch 60m, Natural Soil 30m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>William Trace, Natural Soil 258m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Margaret Harry Trace, Natural Soil 213m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>William Charles Trace, Natural Soil 311m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Hamilton Trace, Pitch 1029m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Hamilton Branch Trace, Pitch 82m, Natural Soil 1012m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Killdeer Branch Trace, Pitch 381m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Ablack Trace 792.7m Pitch, 91.5m Gravel 1097.6m, Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Ablack Settlement Trace, 1384m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Abass Trace 205.8m Pitch, 536.6m Gravel, 499.7m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balgobin Trace, 168m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balgobin Diversion Trace, 290 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bhajandass Trace, 426.8m Pitch</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bidassie Trace, 303m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bhagrattee Trace, 548.8m Pitch, 61m Gravel, 1042.7m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balata Trace, 503 Pitch, 91.5m Gravel, 472.6m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balfour Trace , 792.7m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bharat Trace, 1494 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Choonia Trace, 259 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Colenso Trace, 945m Pitch, 202 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Cemetery Trace, 329m Pitch, 1120m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Charuma Trace, 1274m Pitch</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Charuma Junction Trace, 1570m Asphalt</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Cushe Trace, 1007m Asphalt, 335m Pitch, 213 Gravel, 433m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Dos Ramos Trace, 85.4m Pitch, 177m Gravel, 1158.6m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Euroza Trace, 853.7m Pitch, 45.7m Gravel</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Jankee Trace, 370m Pitch</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Jankee Branch Trace 91.5m, 227m Gravel, 183 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Jim Trace, 457 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Jairam Trace, 732 m Asphalt, 731m Pitch, 91.5m Gravel, 420m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Jairam Branch Trace, 40m Pitch, 701 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Knothill Trace, 127m Pitch, 57m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lutchmintia Trace, 366m Pitch</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lawrence Jones Trace, 1936 Pitch, 305m Gravel</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lawrence Jones Branch Trace, 2332m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lawrence Jones Ext. Trace 91.5m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>London Trace, 320m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Mahabalsingh Trace, 2439m Pitch, 604m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Mahabalsingh Branch Trace #1, 168m Pitch, 602m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Mahabalsingh Branch Trace #2, 1768m Pitch, 488m Gravel</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Mahabalsingh Extension Trace, 485m Oilsand</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Oliver Trace, 610 Pitch, 260m Gravel</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Oliver Branch Trace, 100m Oilsand, 137m Gravel, 1082 Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>O'Laughlin Trace, 737m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>TRACES</b>		
	<i>Pem Bois Trace, 1689m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Ragoonanan Trace, 369m Pitch, 745m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Rampaul Trace, 60m Asphalt, 571m Pitch, 1076m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Rambharath Trace, 1017m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Reid Trace, 61m Pitch, 966m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Roach Trace, 370m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sarran Trace, 201m Pitch, 335m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Ross Trace, 61m Pitch, 108 Gravel, 326m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Self Trace 404m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sewdial Trace, 518m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Sumair Trace, 554.9m Pitch, 192m Natural Soil</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Kernaham Trace</i>	<i>Cocal</i>	<i>Chief Executive Officer</i>
<b>FIXED ASSETS</b>	<b>BRIDGES</b>		
	<i>Guayaguayare Old Road #1 - Concrete</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Trinity Road Bridge #1 - Wooden 25m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Vespry Trace Bridge #1 - Wooden 9.14m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Vespry Ext. Trace Bridge #1 - Wooden 913.93m</i>	<i>Trinity/Guayaguayare</i>	<i>Chief Executive Officer</i>
	<i>Eccles Road Bridge #1 - Concrete .884m</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Road Bridge #2 - Wooden 11.58m</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #1 - Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #2 - Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #3 - Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>

## Mayaro/Rio Claro Regional Corporation Vesting Order, 2000

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>	
<b>FIXED ASSETS</b>	<b>BRIDGES</b>			
	<i>Eccles Trace Bridge #4</i>	- <i>Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #5</i>	- <i>Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #6</i>	- <i>Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #7</i>	- <i>Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Eccles Trace Bridge #8</i>	- <i>Wooden</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Maloney Road Bridge #1</i>	- <i>Concrete 4.57m</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Maloney Road Bridge #2</i>	- <i>Wooden 6.4m</i>	<i>Mayaro-South</i>	<i>Chief Executive Officer</i>
	<i>Cedar Grove Road Bridge #1</i>	- <i>Wooden 6.71m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Sylvan Trace Bridge #1</i>	- <i>Wooden 67.92m</i>	<i>Mayaro Central</i>	<i>Chief Executive Officer</i>
	<i>Ablack Trace Bridge #1</i>	- <i>Concrete 12.5m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Abutment</i>	- <i>Wooden Decking</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balgobin Diversion Trace Br. #1</i>	- <i>Wooden 10m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bhajandass Trace Bridge #1</i>	- <i>Concrete Abutment Wooden Decking 8.25m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Bhagratee Trace Bridge #1</i>	- <i>Wooden 6.5m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balata Trace Bridge #1</i>	- <i>Concrete 7.9m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balata Trace Bridge #2</i>	- <i>Wooden 6.9m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balfour Trace Bridge #1</i>	- <i>Wooden 8.8m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balfour Trace Bridge #2</i>	- <i>Wooden 4m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Balfour Trace Bridge #3</i>	- <i>Wooden 6m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>

Assets Category	Assets Description	Assets Location	Responsibilities Centre/Officer Division
<b>FIXED ASSETS</b>	<b>BRIDGES</b>		
	Colenso Trace Bridge #1 - Wooden 4.27m	Navet/Charuma	Chief Executive Officer
	Charuma Trace Bridge #1 - Concrete 10m	Navet/Charuma	Chief Executive Officer
	Charuma Trace Bridge #2 - Wooden 8m	Navet/Charuma	Chief Executive Officer
	Cushe Trace Bridge #1 - Concrete 7.9m	Navet/Charuma	Chief Executive Officer
	Cushe Trace Bridge #2 - Wooden 7m	Navet/Charuma	Chief Executive Officer
	Dos Ramos Trace Bridge #1 - Wooden 8.5m	Navet/Charuma	Chief Executive Officer
	Jankee Trace Bridge #1 - Wooden 8.2m	Navet/Charuma	Chief Executive Officer
	Jankee Trace Branch Bridge #1 - Wooden 5.5m	Navet/Charuma	Chief Executive Officer
	Jairam Trace Bridge #1 - Wooden - Concrete 13m	Navet/Charuma	Chief Executive Officer
	Jairam Trace Bridge #2 - Wooden - Concrete 10.98m	Navet/Charuma	Chief Executive Officer
	Jairam Trace Branch Bridge #1 - Wooden 5.5m	Navet/Charuma	Chief Executive Officer
	Lutchminia Trace Bridge #1 - Wooden & - Concrete 8.8m	Navet/Charuma	Chief Executive Officer
	Lutchminia Trace Bridge #2 - Wooden & - Concrete 6m	Navet/Charuma	Chief Executive Officer
	Lawrence Jones Branch Br. #1 - Wooden 5.49m	Navet/Charuma	Chief Executive Officer
	Mahabalsingh Trace Branch Br. #1 - Wooden & - Concrete 11.28M	Navet/Charuma	Chief Executive Officer
	Oliver Branch Trace Bridge #1 - Wooden	Navet/Charuma	Chief Executive Officer
	Pem Bois Trace Bridge #1 - Wooden	Navet/Charuma	Chief Executive Officer
	Rampaul Trace Bridge #1 - Wooden 7.4m	Navet/Charuma	Chief Executive Officer
	Rampaul Trace Bridge #2 - Wooden 6.1m	Navet/Charuma	Chief Executive Officer

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>BRIDGES</b>		
	Reid Trace Bridge #1	- Wooden 7.9m Navet/Charuma	Chief Executive Officer
	Ross Trace Bridge #1	- Wooden 12.2m Navet/Charuma	Chief Executive Officer
	Sackeer Trace Bridge #1	Wooden & - Concrete 6.09m Navet/Charuma	Chief Executive Officer
	Sampath Trace Bridge #1	- Wooden 8.2m Navet/Charuma	Chief Executive Officer
	Sanchoo Trace Bridge #1	- Wooden 7.9m Navet/Charuma	Chief Executive Officer
	Sirjue Ext. Trace Bridge #1	- Wooden 7.9m x 7.3m Navet/Charuma	Chief Executive Officer
	Tuerro Trace Bridge #1	- Wooden 15m Navet/Charuma	Chief Executive Officer
	Tabaquite/Charuma Tr. Bridge #1	- Wooden 5m Navet/Charuma	Chief Executive Officer
	Tabaquite/Charuma Tr. Bridge #2	- Wooden Navet/Charuma	Chief Executive Officer
	Tabaquite/Charuma Tr. Bridge #3	- Wooden 7m Navet/Charuma	Chief Executive Officer
	Bharat Ext. Trace Bridge #1	- Wooden 6m Navet/Charuma	Chief Executive Officer
	Crisendial Trace Bridge #1	- Wooden 8.5m Navet/Charuma	Chief Executive Officer
	Greenaway Trace Bridge #1	- Wooden 9.45m Navet/Charuma	Chief Executive Officer
	Greenaway Trace Bridge #2	- Wooden 9.45m Navet/Charuma	Chief Executive Officer
	Heminez Trace Bridge #1	- Wooden 7.5m Navet/Charuma	Chief Executive Officer
	Joseph Trace Bridge #1	- Wooden 8.2m Navet/Charuma	Chief Executive Officer
	Martin Saza Trace Bridge #1	- Wooden 11m Navet/Charuma	Chief Executive Officer
	Soomrah Trace Bridge #1	- Wooden 8.5m Navet/Charuma	Chief Executive Officer
	Fitts Road Bridge #1	- Wooden 9.5m Navet/Charuma	Chief Executive Officer

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>	
<b>FIXED ASSETS</b>	<b>BRIDGES</b>			
	<i>Fitts Road Bridge #2</i>	- <i>Wooden 7.9m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lassalle Road Bridge #1</i>	- <i>Concrete</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Martin Saza Road Bridge #1</i>	- <i>Wooden 7.9m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Martin Saza Road Bridge #2</i>	- <i>Wooden 7.3m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Martin Saza Road Bridge #3</i>	- <i>Wooden 9.1m</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Caltoo Road Bridge #1</i>	- <i>Concrete</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Wade Road Bridge #1</i>	- <i>Concrete</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Brigand Hill Trace Bridge #3</i>	- <i>Wooden</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Caltoo Trace Bridge #1</i>	- <i>Concrete</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Lagoon Trace Bridge #3</i>	- <i>Wooden</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Peter Trace Bridge #3</i>	- <i>Wooden</i>	<i>Navet/Charuma</i>	<i>Chief Executive Officer</i>
	<i>Archer Trace Bridge #4</i>	- <i>Wooden 10m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Cazabon Trace Bridge #1</i>	- <i>Wooden 5.5m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Moonan Trace Bridge #1</i>	- <i>Wooden 6m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro Trace Bridge #1</i>	- <i>Wooden 12.5m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Sarwansingh Trace Bridge #1</i>	- <i>Wooden 8m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Trace Bridge #1</i>	- <i>Wooden 10m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Trace Branch'Bridge #1</i>	- <i>Wooden 10m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Trace Branch'Bridge #2</i>	- <i>Wooden 9.5m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>
	<i>Trebenny Trace Branch'Bridge #3</i>	- <i>Wooden 9.m</i>	<i>Ecclesville</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>BRIDGES</b>		
	<i>Legendre Trace Bridge #1</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>Legendre Trace Bridge #2</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>Legendre Trace Bridge #3</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>North Boundary Tr. Bridge #1</i>	- Wooden 5.79m Ecclesville	Chief Executive Officer
	<i>North Boundary Tr. Bridge #2</i>	- Wooden 11.28m Ecclesville	Chief Executive Officer
	<i>North Boundary Tr. Bridge #3</i>	- Wooden 11.28m Ecclesville	Chief Executive Officer
	<i>Pattigun Trace Bridge #1</i>	- Wooden 6.09m Ecclesville	Chief Executive Officer
	<i>Pattigun Trace Bridge #2</i>	- Wooden 7.4m Ecclesville	Chief Executive Officer
	<i>Titus Trace Bridge #1</i>	- Wooden 7.93m Ecclesville	Chief Executive Officer
	<i>Legendre Road Bridge #1</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>Legendre Road Bridge #2</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>Legendre Road Bridge #3</i>	- Concrete Ecclesville	Chief Executive Officer
	<i>Rio Claro/Mayaro Branch Road Bridge #1</i>	- Wooden 7.9m Ecclesville	Chief Executive Officer
	<i>Archer Trace Bridge #1</i>	- Wooden 4.5m Ecclesville	Chief Executive Officer
	<i>Archer Trace Bridge #2</i>	- Wooden 9.5m Ecclesville	Chief Executive Officer
	<i>Archer Trace Bridge #3</i>	- Wooden 11m Ecclesville	Chief Executive Officer
	<i>Abdul Trace Bridge #1</i>	- Wooden 7.93m Rio Claro	Chief Executive Officer
	<i>Abdul Trace Bridge #2</i>	- Concrete 7.4m Rio Claro	Chief Executive Officer
	<i>Old Railway Bridge #1</i>	- Wooden 4.27m Rio Claro	Chief Executive Officer

**Mayaro/Rio Claro Regional Corporation Vesting Order, 2000**

1007

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>BRIDGES</b>		
	<i>Bristol Road Bridge #1</i>	<i>- Wooden 8.53m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Bhagoo Branch Tr. Bridge #1</i>	<i>- Wooden 7.92m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Cascadoux Trace Bridge #1</i>	<i>- Wooden 5.49m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Cascadoux Trace Bridge #2</i>	<i>- Wooden 6.1m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Chrysostom Trace Bridge #1</i>	<i>- Wooden 8.23m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Dhunda Trace Bridge #1</i>	<i>- Wooden 9.75m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mafeking Road Bridge #1</i>	<i>- Concrete 8.53m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Mafeking Branch Road Bridge #1</i>	<i>- Wooden 7.92m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>North West Trace Bridge #1</i>	<i>- Concrete 5.49m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Point Radix Road Bridge #1</i>	<i>- Concrete 6.71m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Rio Claro-Mayaro Road (Bristol End) Bridge #1</i>	<i>- Wooden 7.92m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Sieudath Trace Bridge #1</i>	<i>- Wooden 4.3m Ortoire/Mafeking</i>	<i>Chief Executive Officer</i>
	<i>Beharry Trace Bridge #1</i>	<i>- Concrete 9.14m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Beharry Trace Bridge #2</i>	<i>- Wooden 9.5m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Campbell Trace Bridge #1</i>	<i>- Concrete 7.5m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Campbell Trace Bridge #2</i>	<i>- Concrete 6m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Campbell Trace Bridge #3</i>	<i>- Concrete 8m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Dades Ext. Trace Bridge #1</i>	<i>- Wooden 10.34m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Dades Ext. Trace Bridge #2</i>	<i>- Wooden 9.76m Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>	
<b>FIXED ASSETS</b>	<b>BRIDGES</b>			
	<i>Killdeer Trace Bridge #1</i>	- <i>Wooden 12.2m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Killdeer Trace Bridge #2</i>	- <i>Wooden 10.97m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Killdeer Trace Bridge #3</i>	- <i>Wooden 7.32m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Latchram Trace Bridge #1</i>	- <i>Wooden 7.28m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lazzari Diversion Trace Bridge #1</i>	- <i>Wooden 7.93m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lazzari Road Bridge #1</i>	- <i>Wooden 8.85m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lyng Trace Bridge #1</i>	- <i>Concrete 13.72m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Lyng Trace Bridge #2</i>	- <i>Wooden 9.15m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mahangasingh Trace Bridge #1</i>	- <i>Wooden 7.6m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Mahangasingh Br. Trace Bridge #1</i>	- <i>Wooden 7.32m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Paymar Branch Tr. Bridge #1</i>	- <i>Wooden 8.53m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Paymar Branch Tr. Bridge #2</i>	- <i>Concrete 9.75m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace Bridge #1</i>	- <i>Concrete 12.8m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace Bridge #2</i>	- <i>Wooden 6.1m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace Bridge #3</i>	- <i>Wooden 6.4m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>
	<i>Poole Valley Trace Bridge #4</i>	- <i>Wooden 10.97m</i>	<i>Fonrose/Dades Settlement</i>	<i>Chief Executive Officer</i>

**Mayaro/Rio Claro Regional Corporation Vesting Order, 2000**

1009

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>OFFICE FURNITURE</b>		
	<i>Two (2) Upholstered Steel Conference Type Chairs</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Eighteen (18) Upholstered Steel Chairs with arm (Ordinary)</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Wooden Chairs with Padded Seats</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Twenty-Six (26) Executive Swivel Chairs</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Thirteen (13) Typist Chairs</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Ten (10) Waiting Room Chairs with Arm Rest</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Eleven (11) Metal Conference Type Tables 90cm x 180cm</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Wooden Table 120cm x 72 cm</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Metal frame table 90cm x 91 cm</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Seven (7) Wooden Cupboards</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Steel Cupboards</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Short Wooden Cupboard</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Nineteen (19) Wooden Desks - 3 Drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Wooden Desk - 6 drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Steel Desks</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Secretaries Desks</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Desk Tidy</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Twenty-Two (22) Wooden Dips</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Double Pedestal Desks</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Wooden Stools</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>

*Mayaro/Rio Claro Regional Corporation Vesting Order, 2000*

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>OFFICE FURNITURE</b>		
	<i>Forty (40) Single Pedestal Desks</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Four (4) Wooden Benches</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Draughtsman Table</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Two (2) Executive Desks</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Wooden (3) Tier Trolley</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Twenty (20) Waste Paper Bins</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Steel Desk - 3 drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Two (2) Wooden Desks - 2 drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) wooden Desk - 3 drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Four (4) Upholstered Chairs</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Wooden Benches</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Long Table</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Two (2) Built-In Cupboards</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Wooden Dips</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Waste Paper Bins</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Sixteen (16) Fire King - 25 Filing Cabinets</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Five (5) Schwab Filing Cabinets</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Leabank Filing Cabinets</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Misc. - 4 drawers Steel Filing Cabinets</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>

**Mayaro/Rio Claro Regional Corporation Vesting Order, 2000**

1011

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>OFFICE FURNITURE</b>		
	One (1) Cellular Phone	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Seven (7) Pagers	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Eleven (11) Cardex Filing Cabinets	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Two (2) Adler Manual Typewriters Serial # 32063727 & 30461130	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Universal 200 Manual Typewriter Serial # 32068728	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Olympia Manual Typewriter Serial # M85318381	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Four (4) Panasonic 7000 Electronic Typewriters Serial Nos. 3JM37B14564 3JM37B 14565, 3JM37B 14547, 3JM37B 14555	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Two (2) Cannon Electrical Typewriters Serial Nos. HA 2051128, HA 2051364	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Casio Calculator Serial No. 6511525	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Five (5) Quartz Wall Clocks	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Ricoh FT 4418 Photocopier Serial No. 2593060270	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Gott. Water Cooler - . Five (5) Gals	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Cannon Faxphone Serial No. 03204MBM	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Two (2) Gestetner Duplicating Machines Serial No. E 612357	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Fourteen (14) Citizens Calculators Serial Nos. 20707097, 20707098 , 20707457, 20767099, 20707458, 20707460, 20707100, 20808017, 20808019, 20808016, 20808476, 20808020, 20808479	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Four (4) Stamp Racks	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	One (1) Memo Holder	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer
	Eleven (11) Call Card Holders	Mayaro-Rio Claro Regional Corporation	Chief Executive Officer

*Mayaro/Rio Claro Regional Corporation Vesting Order, 2001*

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>FIXED ASSETS</b>	<b>OFFICE FURNITURE</b>		
	<i>One (1) Laser Jet Printer</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Revolving Stamp Rack</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Motorola Base Station (NEMA)</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Five (5) Micro Computers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Two (2) Matrix Printers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Ten (10) Diskettes</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Voltage Regulators</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Four (4) Cannon - 12 Digit Calculators</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) - 22 Litres Non-Electrical Water Coolers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Silence Bell</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Platform Scale Complete with weights 2-50Lbs., 1 - 100lbs., 1 -150 lbs., 1-300 lbs.</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Coffre Forte National Safe - 4 drawers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Citizens Calculator Serial No. 10505178</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Leabank - 4 drawer Filing Cabinet</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Mitshiba Quartz Wall Clock</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Gott. Water Cooler</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Five (5) Handsets with Chargers</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Three (3) Mobiles</i>	<i>Mayaro-Rio Claro</i>	

<i>Assets Category</i>	<i>Assets Description</i>	<i>Assets Location</i>	<i>Responsibilities Centre/Officer Division</i>
<b>APPLIANCES</b>			
	<i>Twelve (12) Desk Fans AML</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>Six (6) Pedestal Fans</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) White Westing House Refridgerator 12 Cubic</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Admiral Refridgerator 12 Cubic No. 342291</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Electric Kettle</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Admiral 12 Cubic Refridgerator Serial No. 304315</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Poman Desk Fan</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Whirlpool Refridgerator</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Cuisine Stove</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
	<i>One (1) Kelvinator Refridgerator</i>	<i>Mayaro-Rio Claro Regional Corporation</i>	<i>Chief Executive Officer</i>
<b>ARMS</b>			
	<i>One (1) Taurus - .38 Revolver</i>	<i>Rio Claro Policè Station</i>	<i>Chief Executive Officer</i>
<b>JEWELLRY</b>			
	<i>One (1) Gold Chain ( Chairman)</i>	<i>Bank of Nova Scotia, Rio Claro</i>	<i>Chief Executive Officer</i>

**LIABILITIES OF THE MAYARÓ-RIO CLARO REGIONAL CORPORATION**  
**AS PER REQUESTED RE: MEMORANDUM LG: 20/13/36 DATED**  
**MARCH 21, 1994 AND SUBSEQUENT MEMORANDUM DATED**  
**DECEMBER 24, 1997**

(1) *Monies owed to Suppliers of Goods and Services (Including Outstanding Commitments) and Outstanding Contractual Obligations and Commitments*

<i>W.A.S.A</i>	(a)	<i>Recreation Grounds</i>	-	<i>181,154.49</i>
	(b)	<i>Cemeteries</i>	-	<i>25.00</i>
	(c)	<i>Markets</i>	-	<i>5,853.48</i>
	(d)	<i>Public Convenience</i>	-	<i>18,713.05</i>
	(e)	<i>Office Building</i>	-	<i>16,847.64</i>
	(f)	<i>Disposal of Faecal Matter</i>	-	-
		<b>Total:-</b>		<b><i>222,593.66</i></b>
		<i>T. &amp; T.E.C.</i>		<i>48,292.38</i>
		<i>Sundry Creditors - Commitments</i>		<i>753,225.00</i>

(2) *Arrears of Wages and Salaries or Emoluments to Employees:-*

(a)	<i>1987 - 1992 (Arrears of Cola)</i> <i>(This is an approximate figure since the fire in 1993 destroyed records of the Nariva-Mayaro County Council and the Mayaro-Rio Claro Regional Corporation)</i>	-	<i>35,000.00</i>
(b)	<i>Arrears of Shift Premium</i> <i>(See Explanation at (2a))</i>	-	-
(c)	<i>Arrears of Travelling</i> <i>(as at September 30, 1994 -</i> <i>(See Explanation at (2a))</i>	-	-
(d)	<i>Arrears of C.O.V.</i>	-	-
(e)	<i>Arrears of O.T. for Watchmen</i>	-	-
(f)	<i>Arrears of Sick Leave Bonus</i>	-	<i>43,680.83</i>
(g)	<i>Unclaimed Wages</i>	-	<i>6,089.45</i>

(3) *Outstanding Gratuity/Retirement Benefits:-*

*Retirement Fund (as December 24, 1997)* - 29,932.19

*Other Deposits* - 116,203.97

(4) *Unpresented Cheques as at November, 1997* - 704,102.42

*It is to be noted that the fire in September, 1993 destroyed most of the records of the Nariva-Mayaro County Council and the Mayaro-Rio Claro Regional Corporation.*

*GRAND TOTAL:-* - \$1,959,119.90

Made this 29th day of December, 2000.

M. LOOK LOY  
*Acting Secretary to Cabinet*

Laid before the House of Representatives this 2nd day of March,  
2001:

D. DOLLY  
*Acting Clerk of the House*

Laid before the Senate this 6th day of March, 2001.

N. COX  
*Clerk of the Senate*